

**Flood Control Project Maintenance
Levee Inspections**

LMA District Cover Sheet

Spring 2010 Levee Inspection Results

Yolo County Service Area 6

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections
Unit Cover Sheet
Spring 2010 Levee Inspection Results
Yolo County Service Area 6**

Waterway			Bank	Unit Miles
Unit No. 01 Right Bank of Sacramento River at Knights Landing			Right	5.97
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/5/2010 - 5/5/2010			
DWR Inspector	John Williamson			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Right Bank of Sacramento River at Knights Landing						Right	5.97	04/05/2010 05/05/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.20	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.799142 ° -121.724450 °	38.801361 ° -121.722054 °	3
2	0.00	0.20	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.799154 ° -121.724447 °	38.801369 ° -121.722054 °	2
3	0.00	0.00	Earthen Levee	Animal Control	WS	M	No rodents visible, but rodent burrows visible; need to backfill and compact or grout borrows.	38.799186 ° -121.724440 °	38.799186 ° -121.724440 °	4
4	0.04	0.20	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.799638 ° -121.724004 °	38.801356 ° -121.722079 °	5
5	0.12	0.20	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.800560 ° -121.723324 °	38.801368 ° -121.722054 °	6 Y
6	0.15	0.15	Earthen Levee	Trim / Thin Trees	LS	M	Thin trees to allow visibility of the ground and room to flood fight.	38.800828 ° -121.722903 °	38.800828 ° -121.722903 °	30 Y
7	0.15	0.15	Earthen Levee	Encroachments	WS	PO	Buildings	38.800828 ° -121.722902 °	38.800828 ° -121.722902 °	29 Y
8	0.22	0.26	Earthen Levee	Encroachments	LS	PO	Buildings Inspector Comments: RV park runs on and along levee to bridge	38.801500 ° -121.721878 °	38.801613 ° -121.721328 °	28 Y
9	0.31	0.33	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: This is a two year old home. I have talked to the owner about a permit and he continues to landscape the landside slope with no permit. Owner has added fence across levee. Gave her an application, did field investigation report.	38.801720 ° -121.720447 °	38.801840 ° -121.720030 °	27 Y
10	0.35	0.39	Earthen Levee	Encroachments	LS	PO	Buildings Inspector Comments: apartments with chainlink fence with lathe woven into it.	38.801967 ° -121.719727 °	38.802105 ° -121.718963 °	26 Y
11	0.50	0.57	Earthen Levee	Encroachments	WS	PO	Landscaping	38.802238 ° -121.716875 °	38.801960 ° -121.715700 °	24 Y
12	0.51	0.57	Earthen Levee	Encroachments	LS	PO	Buildings	38.802172 ° -121.716705 °	38.801958 ° -121.715758 °	25 Y
13	0.57	0.71	Earthen Levee	Encroachments	LS	CO	Landscaping Inspector Comments: oleander hedge	38.801968 ° -121.715707 °	38.801077 ° -121.713335 °	22 Y
14	0.57	0.65	Earthen Levee	Encroachments	WS	PO	Buildings Inspector Comments: yolo sutter boat club	38.801965 ° -121.715705 °	38.801468 ° -121.714348 °	23 Y
15	0.65	3.99	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.801460 ° -121.714350 °	38.771039 ° -121.691320 °	7

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Right Bank of Sacramento River at Knights Landing						Right	5.97	04/05/2010 05/05/2010	John Williamson	
LMR No	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
16	0.65	3.99	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.801460 ° -121.714350 °	38.771037 ° -121.691322 °	8
17	0.79	0.79	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.800605 ° -121.711901 °	38.800605 ° -121.711901 °	50
18	0.96	0.96	Earthen Levee	Animal Control	WS	M	Exterminate rodents and backfill and compact or grout burrows.	38.800215 ° -121.709055 °	38.800215 ° -121.709055 °	51
19	0.97	1.14	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.800188 ° -121.708918 °	38.800577 ° -121.705830 °	21 Y
20	1.18	1.34	Earthen Levee	Vegetation	LS	M	Remove the wild growth other than native grasses from the levee slopes.	38.800778 ° -121.705135 °	38.802058 ° -121.702633 °	20 Y
21	1.78	1.78	Earthen Levee	Encroachments	WS	M	Prunings	38.797916 ° -121.697980 °	38.797916 ° -121.697980 °	9 Y
22	1.91	1.91	Earthen Levee	Encroachments	LS	PO	Landscaping Inspector Comments: sprinklers trenched into levee slope	38.796394 ° -121.696700 °	38.796394 ° -121.696700 °	10 Y
23	1.99	1.99	Earthen Levee	Encroachments	LS	M	Prunings	38.795518 ° -121.695965 °	38.795518 ° -121.695965 °	19 Y
24	2.07	2.07	Earthen Levee	Encroachments	LS	M	Prunings	38.794347 ° -121.695690 °	38.794347 ° -121.695690 °	18
25	2.22	2.22	Earthen Levee	Encroachments	LS	M	Pipe	38.792499 ° -121.695508 °	38.792499 ° -121.695508 °	40 Y
26	2.24	2.24	Earthen Levee	Encroachments	LS	M	Firewood	38.792283 ° -121.695447 °	38.792283 ° -121.695447 °	39 Y
27	2.25	2.25	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.792128 ° -121.695400 °	38.792128 ° -121.695400 °	41 Y
28	2.30	2.30	Earthen Levee	Trim / Thin Trees	WS	U	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: tree fell across crown, but still accessible. Tree needs to cut up and remove or burned.	38.791321 ° -121.695261 °	38.791321 ° -121.695261 °	52 Y
29	2.62	2.62	Earthen Levee	Encroachments	LS	PO	Buildings	38.786964 ° -121.694239 °	38.786964 ° -121.694239 °	11 Y
30	2.97	2.97	Earthen Levee	Encroachments	LS	M	Prunings	38.782985 ° -121.691518 °	38.782985 ° -121.691518 °	13 Y
31	2.97	2.97	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows.	38.782985 ° -121.691518 °	38.782985 ° -121.691518 °	14
32	3.12	3.19	Earthen Levee	Encroachments	LS	PO	Buildings	38.781828 ° -121.689415 °	38.780852 ° -121.688887 °	12

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway						Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing						Right	5.97	04/05/2010 05/05/2010	John Williamson

LMR No	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
33	3.16	3.16	Earthen Levee	Encroachments	WS	M	Prunings	38.781358 ° -121.689118 °	38.781358 ° -121.689118 °	34
34	3.25	3.25	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: dead tree broken during winter storms, needs to be cleaned up	38.780041 ° -121.688499 °	38.780041 ° -121.688499 °	15 Y
35	3.33	3.33	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight. Inspector Comments: fallen tree from winter storms, needs to be cleaned up	38.779046 ° -121.687839 °	38.779046 ° -121.687839 °	16 Y
36	3.33	3.33	Earthen Levee	Encroachments	WS	C	Prunings	38.779010 ° -121.687797 °	38.779010 ° -121.687797 °	35
37	3.40	3.40	Earthen Levee	Encroachments	LS	M	Prunings	38.778167 ° -121.687357 °	38.778167 ° -121.687357 °	17 Y
38	4.74	4.95	Supplemental	USACE Erosion Survey	WS	U	Inspector Comments: 2009: 5 ft berm, 1.5:1 slope, slumping, silts, 3.21 ft/s [2009 SiteID:SAC_85-4_R]	38.763314 ° -121.684039 °	38.763486 ° -121.687567 °	33 Y
39	5.60	5.65	Earthen Levee	Encroachments	LS	PO	Buildings	38.759620 ° -121.673903 °	38.759412 ° -121.673167 °	1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	5
Start Levee Mile	0.12
End Levee Mile	0.20
Location	Water Side
Category	Earthen Levee
Item	Vegetation
remove all brush except grasses	
johngw_s_20100405_105.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.15
End Levee Mile	0.15
Location	Land Side
Category	Earthen Levee
Item	Trim / Thin Trees
fig tree on landside other trees need to be trimmed	
johngw_s_20100405_104.jpg	



Levee Mile Report Line	7
Start Levee Mile	0.15
End Levee Mile	0.15
Location	Water Side
Category	Earthen Levee
Item	Encroachments
building on waterside	
johngw_s_20100405_103.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

Tuesday, July 06, 2010 15:11

FINAL DATA

Page 4 of 13

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	8
Start Levee Mile	0.22
End Levee Mile	0.26
Location	Land Side
Category	Earthen Levee
Item	Encroachments
RV park trailers and vehicles on levee	
johnngw_s_20100405_107.jpg	



Levee Mile Report Line	9
Start Levee Mile	0.31
End Levee Mile	0.33
Location	Land Side
Category	Earthen Levee
Item	Encroachments
Fence across levee	
johnngw_s_20100405_108.jpg	



Levee Mile Report Line	9
Start Levee Mile	0.31
End Levee Mile	0.33
Location	Land Side
Category	Earthen Levee
Item	Encroachments
landscape on levee slope	
johnngw_s_20100405_109.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	10
Start Levee Mile	0.35
End Levee Mile	0.39
Location	Land Side
Category	Earthen Levee
Item	Encroachments
apartments and fence	
johngw_s_20100518_181.jpg	



Levee Mile Report Line	11
Start Levee Mile	0.50
End Levee Mile	0.57
Location	Water Side
Category	Earthen Levee
Item	Encroachments
on levee crown	
johngw_s_20100518_182.jpg	



Levee Mile Report Line	12
Start Levee Mile	0.51
End Levee Mile	0.57
Location	Land Side
Category	Earthen Levee
Item	Encroachments
houses on levee	
johngw_s_20100518_183.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	13
Start Levee Mile	0.57
End Levee Mile	0.71
Location	Land Side
Category	Earthen Levee
Item	Encroachments

oleanders along shoulder

johngw_s_20100518_184.jpg



Levee Mile Report Line	14
Start Levee Mile	0.57
End Levee Mile	0.65
Location	Water Side
Category	Earthen Levee
Item	Encroachments

yacht club

johngw_s_20100518_185.jpg



Levee Mile Report Line	19
Start Levee Mile	0.97
End Levee Mile	1.14
Location	Land Side
Category	Earthen Levee
Item	Vegetation

vegetation on landside

johngw_s_20100518_186.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	20
Start Levee Mile	1.18
End Levee Mile	1.34
Location	Land Side
Category	Earthen Levee
Item	Vegetation
vegetation on landside	
johnngw_s_20100518_187.jpg	



Levee Mile Report Line	21
Start Levee Mile	1.78
End Levee Mile	1.78
Location	Water Side
Category	Earthen Levee
Item	Encroachments
prunings	
johnngw_s_20100518_188.jpg	



Levee Mile Report Line	22
Start Levee Mile	1.91
End Levee Mile	1.91
Location	Land Side
Category	Earthen Levee
Item	Encroachments
sprinklers and landscape	
johnngw_s_20100518_189.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	23
Start Levee Mile	1.99
End Levee Mile	1.99
Location	Land Side
Category	Earthen Levee
Item	Encroachments

orchard prunings

johnngw_s_20100518_190.jpg



Levee Mile Report Line	25
Start Levee Mile	2.22
End Levee Mile	2.22
Location	Land Side
Category	Earthen Levee
Item	Encroachments

pipe along toe

johnngw_s_20100518_191.jpg



Levee Mile Report Line	26
Start Levee Mile	2.24
End Levee Mile	2.24
Location	Land Side
Category	Earthen Levee
Item	Encroachments

firewood stacked up

johnngw_s_20100518_192.jpg

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	27
Start Levee Mile	2.25
End Levee Mile	2.25
Location	Land Side
Category	Earthen Levee
Item	Animal Control

rodents

johnngw_s_20100518_193.jpg



Levee Mile Report Line	27
Start Levee Mile	2.25
End Levee Mile	2.25
Location	Land Side
Category	Earthen Levee
Item	Animal Control

close up of hole

johnngw_s_20100518_194.jpg



Levee Mile Report Line	28
Start Levee Mile	2.30
End Levee Mile	2.30
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

tree across levee

johnngw_s_20100518_195.jpg

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	28
Start Levee Mile	2.30
End Levee Mile	2.30
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees

water side view

johnwgw_s_20100518_196.jpg



Levee Mile Report Line	29
Start Levee Mile	2.62
End Levee Mile	2.62
Location	Land Side
Category	Earthen Levee
Item	Encroachments

garage at toe

johnwgw_s_20100518_197.jpg



Levee Mile Report Line	30
Start Levee Mile	2.97
End Levee Mile	2.97
Location	Land Side
Category	Earthen Levee
Item	Encroachments

prunings

johnwgw_s_20100518_198.jpg

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected

C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	34
Start Levee Mile	3.25
End Levee Mile	3.25
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
branches from dead trees, water side	
johnngw_s_20100518_200.jpg	



Levee Mile Report Line	35
Start Levee Mile	3.33
End Levee Mile	3.33
Location	Water Side
Category	Earthen Levee
Item	Trim / Thin Trees
winter storm damage	
johnngw_s_20100518_201.jpg	



Levee Mile Report Line	37
Start Levee Mile	3.40
End Levee Mile	3.40
Location	Land Side
Category	Earthen Levee
Item	Encroachments
several piles of prunings	
johnngw_s_20100518_199.jpg	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected
W : Watch/Monitor

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2010

Yolo County Service Area 6

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Right Bank of Sacramento River at Knights Landing	Right	5.97	04/05/2010 05/05/2010	John Williamson

Levee Mile Report Line	38
Start Levee Mile	4.74
End Levee Mile	4.95
Location	Water Side
Category	Supplemental
Item	USACE Erosion Survey
2009: 5 ft berm, 1.5:1 slope, slumping, silts, 3.21 ft/s [2009 SiteID:SAC_85-4_R]	
USACE2009_SAC_85-4_R_2009_09_16-D2P54_small.JPG	

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing W : Watch/Monitor
U : Unacceptable N : Not Inspected